

Date : 30/10/2015
Version : 3



SAFETY DATA SHEET

PRC Prepacked Columns MEP / HEA / PPA HyperCel™ & HyperCel STAR AX

SECTION 1: Identification of the substance/mixture and of the company/undertaking

1.1 Product identifier

Product name : PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

EC number : Mixture.

CAS number : Not applicable.

Part number/Product code : PRC05X050PPAHCEL01, PRC08X100PPAHCEL01, PRC05X050HEAHCEL01, PRC08X100HEAHCEL01, PRC05X050MEPHCEL01, PRC08X100MEPHCEL01, PRC08X100MEPHCEL01; PRCSTARAX1ML, PRCSTARAX5ML

Product description : Prepacked column of cellulose beads suspended in isopropanol aqueous solution.

Product type : Mixture. Suspended solid in carrier solution.

Other means of identification : Chromatographic (sorbert) solid suspended in a carrier solution (24% (v/v) propan-2-ol and (100 mM) sodium phosphate aqueous).

1.2 Relevant identified uses of the substance or mixture and uses advised against

Purification of biomolecules by mixed-mode purification. (MEP/HEA/PPA).
Purification of biomolecules by ion exchange chromatography. (STAR AX).

1.3 Details of the supplier of the safety data sheet

Supplier : Pall BioSeptra, Division of Pall France
48 Avenue des Genottes
F-95800 Cergy St Christophe
+33 (0)1 34 20 78 00
www.pall.com

Contact in Europe : Pall Europe Limited
5 Harbourgate Business Park
Southampton Road
Portsmouth, Hants, PO6 4BQ
UK
Tel +44 (0)23 9233 8491

e-mail address of person responsible for this SDS : reach_coordinator@pall.com

1.4 Emergency telephone number

Telephone number : CHEMTREC, U.S. : 1-800-424-9300
International: +1-703-527-3887

Hours of operation : 24 hours/day, 7 days/week

Country of Origin: : France



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 2/14

SECTION 2: Hazards identification

2.1 Classification of the substance or mixture

Product definition : Chromatographic (sorbent) solid suspended in a carrier solution (24% (v/v) propan-2-ol and (100 mM) sodium phosphate aqueous).

Classification according to Regulation (EC) No. 1272/2008 [CLP/GHS]

Flam. Liq. 3, H226

Eye Irrit. 2, H319

STOT SE 3, H336

The product is classified as hazardous according to Regulation (EC) 1272/2008 as amended.

See Section 16 for the full text of the H statements declared above.

See Section 11 for more detailed information on health effects and symptoms.

2.2 Label elements

Hazard pictograms



Signal word

: Warning

Hazard statements

: H226 - Flammable liquid and vapour.
H319 - Causes serious eye irritation.
H336 - May cause drowsiness or dizziness.

Precautionary statements

General

: Not applicable.

Prevention

: P280 - Wear protective gloves. Wear eye or face protection.
P210 - Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking.
P241 - Use explosion-proof electrical, ventilating, lighting and all material-handling equipment.

Response

: P304 + P340 - IF INHALED: Remove person to fresh air and keep comfortable for breathing.
P303 + P361 + P353 - IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water or shower.

Storage

: P235 - Keep cool.

Disposal

: P501 - Dispose of contents and container in accordance with all local, regional, national and international regulations.

Supplemental label elements

: Not applicable.

Annex XVII - Restrictions on the manufacture, placing on the market and use of certain dangerous substances, mixtures and articles

: Not applicable.

Special packaging requirements



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 3/14

SECTION 2: Hazards identification

Containers to be fitted with child-resistant fastenings : Not applicable.

Tactile warning of danger : Not applicable.

2.3 Other hazards

Other hazards which do not result in classification : None known.

SECTION 3: Composition/information on ingredients

3.2 Mixtures : Chromatographic (sorbent) solid suspended in a carrier solution (24% (v/v) propan-2-ol and (100 mM) sodium phosphate aqueous).

Product/ingredient name	Identifiers	%	Regulation (EC) No. 1272/2008 [CLP]	Type
Carrier solution: Propan-2-ol	EC: 200-661-7 CAS: 67-63-0 Index: 603-117-00-0	24	Flam. Liq. 2, H225 Eye Irrit. 2, H319 STOT SE 3, H336 (Narcotic effects)	[1] [2]
100 mM sodium phosphate aqueous solution	EC: 231-449-2 CAS: 10049-21-5	76	Skin Irrit. 2, H315 Eye Irrit. 2, H319 STOT SE 3, H335 (Respiratory tract irritation)	[1]
Chromatography sorbent: Cellulosic solid		100		
Hardware: Polypropylene	CAS: 9003-07-0	-	Not classified.	-
Ethene, homopolymer	CAS: 9002-88-4	-	Not classified.	-

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment, are PBTs or vPvBs or have been assigned a workplace exposure limit and hence require reporting in this section.

Type

[1] Substance classified with a health or environmental hazard

[2] Substance with a workplace exposure limit

[3] Substance meets the criteria for PBT according to Regulation (EC) No. 1907/2006, Annex XIII

[4] Substance meets the criteria for vPvB according to Regulation (EC) No. 1907/2006, Annex XIII

[5] Substance of equivalent concern

Occupational exposure limits, if available, are listed in Section 8.

See Section 16 for the full text of the H statements declared above.

SECTION 4: First aid measures

4.1 Description of first aid measures

Eye contact : Immediately flush eyes with plenty of water, occasionally lifting the upper and lower eyelids. Check for and remove any contact lenses. Continue to rinse for at least 20 minutes. Get medical attention.

Inhalation : Risk through inhalation unlikely due to the small size of the product and the quantity of hazardous material present. Remove patient from source of exposure to fresh air. If patient is feeling unwell or exhibiting symptoms, get medical attention.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 4/14

SECTION 4: First aid measures

- Skin contact** : Flush contaminated skin with plenty of water. Get medical attention if severe irritation or other symptoms occur.
- Ingestion** : Unlikely route of exposure due to size and nature of product. Rinse mouth with water. If material has been ingested give small quantities of water to drink. Do not induce vomiting unless instructed to do so by medical personnel. Get medical attention if patient exhibits adverse effects.
- Protection of first-aiders** : No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation.

4.2 Most important symptoms and effects, both acute and delayed

Potential acute health effects

- Eye contact** : Causes serious eye irritation.
- Inhalation** : Can cause central nervous system (CNS) depression. May cause drowsiness or dizziness.
- Skin contact** : No known significant effects or critical hazards.
- Ingestion** : Can cause central nervous system (CNS) depression.

Over-exposure signs/symptoms

- Eye contact** : Adverse symptoms may include the following:
pain or irritation
watering
redness
- Inhalation** : Adverse symptoms may include the following:
nausea or vomiting
headache
drowsiness/fatigue
dizziness/vertigo
unconsciousness
- Skin contact** : No known significant effects or critical hazards.
- Ingestion** : No known significant effects or critical hazards.

4.3 Indication of any immediate medical attention and special treatment needed

- Notes to physician** : Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.
- Specific treatments** : No specific treatment.

SECTION 5: Firefighting measures

5.1 Extinguishing media

- Suitable extinguishing media** : Use dry chemical, CO₂, water spray (fog) or foam.
- Unsuitable extinguishing media** : Do not use water jet.

5.2 Special hazards arising from the substance or mixture



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 5/14

SECTION 5: Firefighting measures

Hazards from the substance or mixture : No specific hazard due to the size of the product and quantity of flammable material present.

Hazardous thermal decomposition products : Decomposition products may include the following materials:
carbon dioxide
carbon monoxide
phosphorus oxides
metal oxide/oxides

5.3 Advice for firefighters

Special protective actions for fire-fighters : Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable training. Move containers from fire area if this can be done without risk. Use water spray to keep fire-exposed containers cool.

Special protective equipment for fire-fighters : Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode. Clothing for fire-fighters (including helmets, protective boots and gloves) conforming to European standard EN 469 will provide a basic level of protection for chemical incidents.

SECTION 6: Accidental release measures

6.1 Personal precautions, protective equipment and emergency procedures

For non-emergency personnel : Minimal risk due to the size of the product and the quantity of hazardous material present. No action shall be taken involving any personal risk without suitable training. Avoid sources of ignition in the immediate area such as sparks or naked flames. Ventilate to remove fumes. Handle spilt material using appropriate PPE.

For emergency responders : If specialised clothing is required to deal with the spillage, take note of any information in Section 8 on suitable and unsuitable materials. See also the information in "For non-emergency personnel".

6.2 Environmental precautions

: Avoid dispersal of spilt material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).

6.3 Methods and material for containment and cleaning up

Spill : Unlikely due to the size of the product and the quantity of hazardous material present. Stop leak if without risk. Move containers from spill area. Use spark-proof tools and explosion-proof equipment. Approach the release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations. Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilt product.

6.4 Reference to other sections

: See Section 1 for emergency contact information.
See Section 8 for information on appropriate personal protective equipment.
See Section 13 for additional waste treatment information.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 6/14

SECTION 7: Handling and storage

The information in this section contains generic advice and guidance. The list of Identified Uses in Section 1 should be consulted for any available use-specific information provided in the Exposure Scenario(s).

7.1 Precautions for safe handling

- Protective measures** : See section 8 for advice on PPE. Avoid contact with skin, eyes and clothing. Do not inhale fumes. Store in original container. Store in a cool, dry place away from sparks, naked flames or other sources of ignition.
- Advice on general occupational hygiene** : Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. See also Section 8 for additional information on hygiene measures.

7.2 Conditions for safe storage, including any incompatibilities

Store between 2 - 8 °C (36 - 46°F) for MEP, HEA and PPA HyperCel and 2 - 30 °C (36 – 86 °F) for HyperCel STAR AX. Store in accordance with local regulations. Store in original container, in a cool well ventilated area away from direct sunlight and ignition sources. Keep away from food, drink and incompatible materials (see section 10).

Seveso Directive - Reporting thresholds (in tonnes)

Danger criteria

Category	Notification and MAPP threshold	Safety report threshold
P5c: Flammable liquids 2 and 3 not falling under P5a or P5b	5000	50000
C6: Flammable (R10)	5000	50000

7.3 Specific end use(s)

- Recommendations** : Not available.
- Industrial sector specific solutions** : Not available.

SECTION 8: Exposure controls/personal protection

The information in this section contains generic advice and guidance. Information is provided based on typical anticipated uses of the product. Additional measures might be required for bulk handling or other uses that could significantly increase worker exposure or environmental releases.

8.1 Control parameters

Occupational exposure limits

Product/ingredient name	Exposure limit values
Isopropyl alcohol	EH40/2005 WELs (United Kingdom (UK), 12/2011). STEL: 1250 mg/m ³ 15 minutes. STEL: 500 ppm 15 minutes. TWA: 999 mg/m ³ 8 hours. TWA: 400 ppm 8 hours.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 7/14

SECTION 8: Exposure controls/personal protection

Recommended monitoring procedures : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment. Reference should be made to monitoring standards, such as the following: European Standard EN 689 (Workplace atmospheres - Guidance for the assessment of exposure by inhalation to chemical agents for comparison with limit values and measurement strategy) European Standard EN 14042 (Workplace atmospheres - Guide for the application and use of procedures for the assessment of exposure to chemical and biological agents) European Standard EN 482 (Workplace atmospheres - General requirements for the performance of procedures for the measurement of chemical agents) Reference to national guidance documents for methods for the determination of hazardous substances will also be required.

DNELs/DMELs

No DNELs/DMELs available.

PNECs

No PNECs available

8.2 Exposure controls

Appropriate engineering controls : Use only with adequate ventilation. Use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory limits. The engineering controls also need to keep gas, vapour or dust concentrations below any lower explosive limits. Use explosion-proof ventilation equipment.

Individual protection measures

Hygiene measures : Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.

Eye/face protection : Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists, gases or dusts. If contact is possible, the following protection should be worn, unless the assessment indicates a higher degree of protection: chemical splash goggles.

Skin protection

Hand protection : Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary. Considering the parameters specified by the glove manufacturer, check during use that the gloves are still retaining their protective properties. It should be noted that the time to breakthrough for any glove material may be different for different glove manufacturers. In the case of mixtures, consisting of several substances, the protection time of the gloves cannot be accurately estimated.

Body protection : Due to the small size of the product and quantity of hazardous material present, body contamination is unlikely. PPE should be selected on the basis of the task being performed. Recommended: Lab Coat.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 8/14

SECTION 8: Exposure controls/personal protection

- Other skin protection** : Large scale skin contamination unlikely due to the size of the product and quantity of hazardous material present.
- Respiratory protection** : Respiratory protection unlikely to be required due to the size of the product and the quantity of hazardous material present.
- Environmental exposure controls** : Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation.

SECTION 9: Physical and chemical properties

Note: The properties listed here are based on the carrier solution.

9.1 Information on basic physical and chemical properties

Appearance

- Physical state** : Liquid. [Suspended solid in a carrier solution.]
- Colour** : Colourless to white.
- Odour** : Alcohol-like.
- Odour threshold** : Not available.
- pH** : Neutral (Propan-2-ol)
- Melting point/freezing point** : Not available.
- Initial boiling point and boiling range** : 80.3°C (azeotrope)
- Flash point** : Closed cup: 24 to 29°C
- Evaporation rate** : >1 (Butyl acetate = 1)
- Flammability (solid, gas)** : Flammable in the presence of the following materials or conditions: open flames, sparks and static discharge.
Slightly flammable in the presence of the following materials or conditions: heat.
- Upper/lower flammability or explosive limits** : Lower: 2% (Propan-2-ol)
Upper: 12.7% (Propan-2-ol)
- Vapour pressure** : 43 hPa @ 20°C (68°F) (Propan-2-ol)
- Vapour density** : >1 [Air = 1]
- Relative density** : <1 [Water = 1]
- Solubility(ies)** : Easily soluble in the following materials: cold water and hot water.
- Partition coefficient: n-octanol/ water** : Not available.
- Auto-ignition temperature** : 425°C (Propan-2-ol)
- Decomposition temperature** : Not available.
- Viscosity** : Not available.
- Explosive properties** : Not available.
- Oxidising properties** : Not available.

9.2 Other information

No additional information.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 9/14

SECTION 10: Stability and reactivity

- 10.1 Reactivity** : The product is non-reactive if used and stored under recommended conditions.
- 10.2 Chemical stability** : The product is stable if used and stored under recommended conditions.
- 10.3 Possibility of hazardous reactions** : Under recommended conditions of storage and use, hazardous reactions will not occur.
- 10.4 Conditions to avoid** : Avoid all possible sources of ignition (spark or flame). Do not pressurise, cut, weld, braze, solder, drill, grind or expose containers to heat or sources of ignition. Do not allow vapour to accumulate in low or confined areas.
- 10.5 Incompatible materials** : Reactive or incompatible with the following materials:
oxidising materials
- 10.6 Hazardous decomposition products** : Under recommended conditions of storage and use, hazardous decomposition products should not be produced.

SECTION 11: Toxicological information

11.1 Information on toxicological effects

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
Isopropyl alcohol	LD50 Dermal	Rabbit	12800 mg/kg	-
	LD50 Oral	Rat	5000 mg/kg	-

Irritation/Corrosion

Product/ingredient name	Result	Species	Score	Exposure	Observation
Isopropyl alcohol	Eyes - Severe irritant	Rabbit	-	100 mg	-
	Skin - Mild irritant	Rabbit	-	500 mg	-
	Eyes - Moderate irritant	Rabbit	-	24 hours 100 mg	-
	Eyes - Moderate irritant	Rabbit	-	10 mg	-

Sensitisation

There is no data available.

Carcinogenicity

IARC: No component of this product present at levels greater than or equal to 0.1% is identified as probable, possible or confirmed human carcinogen by IARC.

Specific target organ toxicity (single exposure)

Product/ingredient name	Category	Route of exposure	Target organs
Isopropyl alcohol	Category 3	Not applicable.	Narcotic effects
Phosphoric acid, monosodium salt, monohydrate	Category 3	Not applicable.	Respiratory tract irritation

Specific target organ toxicity (repeated exposure)

There is no data available.

Aspiration hazard



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 10/14

SECTION 11: Toxicological information

There is no data available.

Information on the likely routes of exposure : Dermal contact. Eye contact. Inhalation. Ingestion.

Potential acute health effects

Eye contact : Causes serious eye irritation.

Inhalation : Can cause central nervous system (CNS) depression. May cause drowsiness or dizziness.

Skin contact : No known significant effects or critical hazards.

Ingestion : Can cause central nervous system (CNS) depression.

Symptoms related to the physical, chemical and toxicological characteristics

Eye contact : Adverse symptoms may include the following:
pain or irritation
watering
redness

Inhalation : Adverse symptoms may include the following:
nausea or vomiting
headache
drowsiness/fatigue
dizziness/vertigo
unconsciousness

Skin contact : No known significant effects or critical hazards.

Ingestion : No known significant effects or critical hazards.

Delayed and immediate effects and also chronic effects from short and long term exposure

Short term exposure

Potential immediate effects : No known significant effects or critical hazards.

Potential delayed effects : No known significant effects or critical hazards.

Long term exposure

Potential immediate effects : No known significant effects or critical hazards.

Potential delayed effects : No known significant effects or critical hazards.

Potential chronic health effects

General : No known significant effects or critical hazards.

Carcinogenicity : No known significant effects or critical hazards.

Mutagenicity : No known significant effects or critical hazards.

Teratogenicity : No known significant effects or critical hazards.

Developmental effects : No known significant effects or critical hazards.

Fertility effects : No known significant effects or critical hazards.

Other information : Not available.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 11/14

SECTION 12: Ecological information

12.1 Toxicity

Product/ingredient name	Result	Species	Exposure
Isopropyl alcohol	Acute LC50 1400000 to 1950000 µg/L Marine water	Crustaceans - Crangon crangon	48 hours
	Acute LC50 4200 mg/L Fresh water	Fish - Rasbora heteromorpha	96 hours

12.2 Persistence and degradability

There is no data available.

12.3 Bioaccumulative potential

Product/ingredient name	LogP _{ow}	BCF	Potential
Isopropyl alcohol	0.05	-	low

12.4 Mobility in soil

Soil/water partition coefficient (K_{oc}) : There is no data available.

Mobility : Not available.

12.5 Results of PBT and vPvB assessment

PBT : Not applicable.

vPvB : Not applicable.

12.6 Other adverse effects : No known significant effects or critical hazards.

SECTION 13: Disposal considerations

The information in this section contains generic advice and guidance. The list of Identified Uses in Section 1 should be consulted for any available use-specific information provided in the Exposure Scenario(s).

13.1 Waste treatment methods

Product

Methods of disposal : The generation of waste should be avoided or minimised wherever possible. Disposal of this product, solutions and any by-products should comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Waste should not be disposed of untreated to the sewer unless fully compliant with the requirements of all authorities with jurisdiction.

Hazardous waste : The classification of the product may meet the criteria for a hazardous waste.

Packaging

Methods of disposal : The generation of waste should be avoided or minimised wherever possible. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 12/14

SECTION 13: Disposal considerations

Special precautions : This material and its container must be disposed of in a safe way. Care should be taken when handling empty containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Vapour from product residues may create a highly flammable or explosive atmosphere inside the container. Do not cut, weld or grind used containers unless they have been cleaned thoroughly internally. Avoid dispersal of spilt material and runoff and contact with soil, waterways, drains and sewers.

SECTION 14: Transport information

	ADR/RID	ADN	IMDG	IATA
14.1 UN number	Not regulated.	Not regulated.	Not regulated.	Not regulated.
14.2 UN proper shipping name	-	-	-	-
14.3 Transport hazard class(es)	-	-	-	-
14.4 Packing group	-	-	-	-
14.5 Environmental hazards	No.	No.	No.	No.
Additional information	-	-	-	-

14.6 Special precautions for user : **Transport within user's premises:** always transport in closed containers that are upright and secure. Ensure that persons transporting the product know what to do in the event of an accident or spillage.

14.7 Transport in bulk according to Annex II of MARPOL 73/78 and the IBC Code : Not available.

SECTION 15: Regulatory information

15.1 Safety, health and environmental regulations/legislation specific for the substance or mixture
[EU Regulation \(EC\) No. 1907/2006 \(REACH\)](#)

[Annex XIV - List of substances subject to authorisation](#)

[Annex XIV](#)

None of the components are listed.

[Substances of very high concern](#)

None of the components are listed.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 13/14

SECTION 15: Regulatory information

Annex XVII - Restrictions on the manufacture, placing on the market and use of certain dangerous substances, mixtures and articles : Not applicable.

Other EU regulations

Europe inventory : Not determined.

Seveso Directive

This product is controlled under the Seveso Directive.

Danger criteria

Category

P5c: Flammable liquids 2 and 3 not falling under P5a or P5b
C6: Flammable (R10)

15.2 Chemical Safety Assessment : This product contains substances for which Chemical Safety Assessments are still required.

SECTION 16: Other information

Abbreviations and acronyms :

- ATE = Acute Toxicity Estimate
- CLP = Classification, Labelling and Packaging Regulation [Regulation (EC) No. 1272/2008]
- DMEL = Derived Minimal Effect Level
- DNEL = Derived No Effect Level
- EUH statement = CLP-specific Hazard statement
- PBT = Persistent, Bioaccumulative and Toxic
- PNEC = Predicted No Effect Concentration
- RRN = REACH Registration Number
- vPvB = Very Persistent and Very Bioaccumulative

Procedure used to derive the classification according to Regulation (EC) No. 1272/2008 [CLP/GHS]

Classification	Justification
Flam. Liq. 3, H226 Eye Irrit. 2, H319 STOT SE 3, H336	On basis of test data Calculation method Calculation method

F - Highly flammable
Xi - Irritant

Full text of abbreviated H statements

H225	Highly flammable liquid and vapour.
H226	Flammable liquid and vapour.
H315	Causes skin irritation.
H319	Causes serious eye irritation.
H335	May cause respiratory irritation.
H336	May cause drowsiness or dizziness.



Pall Corporation

SAFETY DATA SHEET

PRC Columns 5x50 and 8x100 MEP, HEA and PPA HyperCel; PRC Columns 5x50 and 8x100 HyperCel STAR AX

Page: 14/14

SECTION 16: Other information

Full text of classifications [CLP/GHS]	Eye Irrit. 2, H319	SERIOUS EYE DAMAGE/ EYE IRRITATION - Category 2
	Flam. Liq. 2, H225	FLAMMABLE LIQUIDS - Category 2
	Flam. Liq. 3, H226	FLAMMABLE LIQUIDS - Category 3
	Skin Irrit. 2, H315	SKIN CORROSION/IRRITATION - Category 2
	STOT SE 3, H335	SPECIFIC TARGET ORGAN TOXICITY (SINGLE EXPOSURE) (Respiratory tract irritation) - Category 3
	STOT SE 3, H336	SPECIFIC TARGET ORGAN TOXICITY (SINGLE EXPOSURE) (Narcotic effects) - Category 3

History

Date of issue (dd/mm/yyyy) : 30/10/2015

Date of previous issue : 15/05/2015


Version : 3

Revised Section(s) : 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16.

Notice to reader

To the best of our knowledge, the information contained herein is accurate. However, neither the above-named supplier, nor any of its subsidiaries, assumes any liability whatsoever for the accuracy or completeness of the information contained herein.

Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist.

Pall,  and HyperCel are trademarks of Pall Corporation.

® indicates a trademark registered in the USA and ™ indicates a common law trademark.

©Pall Corporation, 2015